

































1.1	HUS-H	h_{nom}	h_1	t_{fix}
	14 x 115	110 mm	$125 \text{ mm} - t_{fix}$	0 ... 5 mm
	14 x 135	110 mm	$145 \text{ mm} - t_{fix}$	0 ... 25 mm
	14 x 160	110 mm	$170 \text{ mm} - t_{fix}$	0 ... 50 mm

1.2	HUS-HF	h_{nom}	h_1	t_{fix}
	14 x 115	110 mm	$125 \text{ mm} - t_{fix}$	0 ... 5 mm



2.1			
			
d_0	$\varnothing 14 \text{ mm}$		



4.1				
	SIW 14-A			
	SIW 22-A			
	SIW 22T-A			
	SI 100			
	65 Nm	